


# CHECKMATE SUPER SUPER


THE PERFECT DYE PENETRANT TESTS KIT



MATCHED CERTIFIED ALUMINIUM TEST-PANELS



PRETT & WHITNEY PSM-5



CERTIFIED NI-CR MATCHED TEST-PANELS

PREFERRED BY INDUSTRY LEADERS
IN INDIA & ABROAD

# **DPT- TESTS PROCEDURE**





# PRE-CLEANING

Pre-clean the surface thoroughly with lint free cloth soaked in cleaner (CL-96) & let it Dry.



### PENETRANT APPLICATION

Apply Dye Penetrant and leave it as it is for recommended dwelling period. (PT-97)



# l F

## PENETRANT REMOVAL

Remove excess Penetrant from area under Test- ensuring that no traces of Dye visible. (CL-96)



## DEVELOPING

Apply Developer uniformly over the surface. (DV-98)






### INSPECTION

Defect, if present, will be visible as bright red indications through the Developer.

# PROCEDURE FOR CHECKMATE PENETRANT TESTING IN ACCORDANCE WITH INTERNATIONAL CODE OF PRACTICE






# SUPER PENETRANT'S STANDARD-DWELLING AND CONTACT PERIOD (MINUTES)

JOBS	FORM OF DEFECTS	MATERIALS			
		ALUMINIUM & ALLOYS	STEEL	BRASS/BRONZE/ COPPER	CARBIDE & HARD TOOLS
Weldments	Cracks	20	30	20	
	Lack of Fusion	20	30	20	
	Porosity	20	30	20	Electrical States
Cast & Die Cast	Shrinkage	10	20	10	
	Porosity	10	20	10	
	Cold Shutts	10	20 ·	15	
Forge	Cracks	20	25	20	. 20
	Laps	20	25	20	
Braze & Soldering	Cracks		4 4 5	20	
	Porosity			20	
All Forms	Fatigue Cracks	20	30	20	30
	Leaks	20	20	20	20

# PROFILES & INDICATIONS OF CHECKMATE PENETRANT TESTS





# SUPER PENETRANT MATERIALS RANGE

# **CLEANERS**

#### 1. CL-96 HF

High flash-nonflammable quick drying solvent for removal of excess penetrant by wipe method. CL-96 HF can also be used for removal of organic contaminations prior and post penetrant testing.

#### 2. CL-96 GP

Low flash-quick drying organic solvent for removal of excess penetrant in solvent wipe method. Free from halogens and chloride.

#### 3. CL-96 GP-I

General purpose cleaning solvent, for pre and post-cleaning of surface, slightly slow drying a moderately Priced for Bulk consumption requirements.

# **PENETRANTS**

#### PT-97

Bright pink/red penetrant for post and pre-cleaning with solvent suitable for all types of weldments, forgings, machined parts for excellent sensitivity & most commonly used.

#### **PT-97 HF**

High sensitivity, high flash, bright contrast red/pink colour dye penetrant for use in solvent cleaning or post Penetrant removal. Ideal for hot objects and explosive zones.

#### PT-97 WW

Bright pink/red directly water washable penetrant for inspection of casts, welds and uneven surfaces, where cleaning of excess penetrant with solvent is not permitted or inconvenient.

# **DEVELOPERS**

#### DV-98

Non halogenated, non aquous solvent suspended white developer for application by spray method.

#### DV-98 HF

High flash solvent suspended white colour developer powder for application where halogenated solvent applications are permitted.

#### DV-98 (D)

Light weight dry developer powder for dry application by dusting/dry spraying/electrostatic deposition. Ideal for areas where wet applications are not permitted.

#### DV-98 (PST

Developer paste for suspention/dissolution in hot water using base stirrer. Ideal for application on Aluminium/ Bronze parts for quick heat decipation imparting a fine coat of developer and for quick inspection.

## PACKING AVAILABLE

Choice of aerosol and non aerosol packs available.

Spray Cans: 320 ML-425-500-ML Cans Non Aerosol Cans 1-Ltrs, 5 Ltrs, 20 Ltrs. Tins.

# CHECKMATEINDIA

(FORMERLY KNOWN AS : CHECKMATE CHEMITALS PVT. LTD.)



Regd Off.: 3964/41, Ajmeri Gate, Delhi-110006

Phone: 011-30114576, 23219576 Fax: 011-23213210 Cell.: 9811618090, 9310065762, 9811319554

Works: 13-MIE-Phase- A, N.H.10, Delhi Rohtak Road, Bahadurgarh.

Distt. Jhajjhar - 124507 (Haryana) Phone : 01276-320058, 267958 Fax : 011-23213210

Email: <checkmate4dpt@gmail.com><projectashok@yahoo.co.in>